

**Nine Mile Creek Watershed District- Site Inspection Report
March 28 thru April 5, 2019**

Inspection Summary

Number of sites inspected =	179
Of inspected, # of sites with no current construction activity =	19
Of inspected, # of sites where construction has not started =	32
Of inspected, # of sites where construction is completed and project will be removed from inspection list =	5
Of inspected, # of sites where vegetation not fully established (remain on inspection list) =	32
Of inspected, # of sites where no site issues were observed =	57
Of inspected, # of sites with action or follow-up required (see below) =	34

Permit #	Project Name	Date of Inspection	Observations	Status
2018-129	Streambank Stabilization, Site A: 7808 Creekridge Circle	29-Mar-19	Boulders placed on outside streambank along access road. Branches and vegetation mats placed on top with erosion control blankets stabilizing exposed soils. A washout has occurred on downstream bank.	Concerns noted for follow-up
2018-127	Home Construction: 8735 Emerson Avenue	29-Mar-19	On site soil stockpiles and disturbed soils need additional perimeter control to prevent sediment washouts to street. Left message with On-Site Contractor.	Action required.
2018-123	Home Construction: 5721 Southwood Drive	4-Apr-19	Home construction in progress. Asphalt driveway remains for construction entrance. Perimeter biologs likely insufficient to contain sediment from large on-site soil stockpiles.	Concerns noted for follow-up
2018-117	Home Construction: 6810 Limerick Lane	5-Apr-19	Home construction in progress. Damaged silt fence overtopped from on-site soil stockpiles. Repair/replace silt fence and remove sediment to washouts to street. Left message with Site Contractor.	Action required.
2018-112	Home Construction: 405 12th Ave North	1-Apr-2019	Foundation construction in progress. Perimeter silt fence damaged and overtopped with soil from large soil stockpiles. Left message with Site Contractor to have repairs made.	Action required.
2018-110	Home Construction: 5905 Tamarac Lane	5-Apr-2019	Home construction in progress. Damaged silt fence and biologs will be repaired/replaced by On-Site Contractor in 48 hours.	Action required.
2018-99	Home Construction: 5120 Kelsey Terrace	5-Apr-2019	Home construction in progress. Silt fence nearing 50% capacity at base of slope in rear yard. On-Site Contractor is currently removing sediment from fence.	Action required.
2018-93	Home Construction: 6334 Coteau Trail	1-Apr-2019	Repair damaged silt fence along side of site and biologs along street. Left message with Site Contractor.	Action required.
2018-86	Home Construction: 6005 Pine Grove Road	5-Apr-2019	Home construction in progress. Repair damaged silt fence in rear and side yard. On-Site Contractor will have silt fence repaired.	Action required.
2018-82	Home Construction: 6608 Cahill Road	5-Apr-2019	Home construction in progress. Perimeter BMPs in place. Construction entrance partially silted. Minor tracking currently to street.	Concerns noted for follow-up
2018-77	Home Construction: 9020 West Bush Lake Road	4-Apr-2019	Home construction complete. Infiltration basin construction in progress. Damaged silt fence along disturbed soils and street needs repair. Left message with On-Site Contractor to have repairs made.	Action required.
2018-71	Home Construction: 3100 West 98 th Street	28-Mar-2019	Home construction complete. Infiltration basin excavation in progress. Damaged perimeter silt fence needs repair. Homeowner will contact Contractor to have silt fence repaired.	Action required.

Permit #	Project Name	Date of Inspection	Observations	Status
2018-59	Solbekken Villas, 5740-5750 Shady Oak Rd.	1-Apr-2019	Building construction and site grading in progress. Damaged perimeter silt fence needs repair. Left message with Site Contractor to have repairs made.	Action required.
2018-56	Budget Truck Rental: 305 American Blvd.	29-Mar-2019	Silt fence remains along narrow strip of disturbed soils.	Concerns noted for follow-up
2018-52	Bren Road Apartments: 11001 Bren Road East	1-Apr-2019	Concrete crushing in progress. Significant dust migrating offsite. Silt fence damaged at several locations. Spoke with On-Site Contractor: will have repairs to silt fence made and crushing operation sprayed with water the following day.	Action required.
2018-47	Woodhill Road Reconstruction	1-Apr-2019	No current construction activity. Previously disturbed soils have been partially stabilized with hydro mulch and erosion control blankets. Perimeter silt fence remains in place along un-stabilized soils.	Concerns noted for follow-up
2018-46	Home Reconstruction: 5300 West 61st Street	5-Apr-2019	Home construction in progress. Damaged perimeter silt fence needs repair. Soil Stockpile remains in rear yard. Left message with Site Contractor.	Action required.
2018-43	Home Reconstruction: 6327 Knoll Dr.	5-Apr-2019	Home construction and driveway installation complete. Disturbed soils partially blanketed and perimeter biologs in place.	Concerns noted for follow-up
2018-41	Acorn Mini Storage: Bloomington	2-Mar-2019	No current construction activity. Install perimeter BMPs along disturbed soils and street. Replace damaged biologs. Left message with Site Contractor	Action required.
2018-18	Normandale Community College, Tunnel and Courtyard Improvements	28-May-2019	Demolition and construction activities in progress. Construction entrance and perimeter BMPs in place. Inlet protection also in place. Inlet protection at center of courtyard insufficient protection Left message with On-Site Contractor or Representative.	Action required.
2018-13	Home Construction: 4501 Dunham Drive	4-Apr-2019	Home construction in progress. Repair damaged silt fence along street or add biologs. Left message with Project Contractor.	Action required.
2018-07	Bloomington Self Storage: 9601 Penn Avenue South	28-Mar-2019	Repair damaged silt fence at ditch culvert inlet, fence is completely down allowing turbid water to flow to-from disturbed soils. Also repair all other damaged sections of silt fence. Install inlet protection or stabilize all disturbed soils. Project Contractor will have repairs made on April 1, 2019	Action required.
2017-124	Home Construction: 5316 Dundee Road	5-Apr-2019	Home construction and driveway installation complete. Slope washouts captured by series of biologs. Disturbed soils need to be stabilized.	Action required.
2017-113	Home Addition: 6116 Eden Prairie Road	5-Apr-2019	Home construction appears complete. Disturbed soils not current stabilized.	Concerns noted for follow-up
2017-94	River Valley Crosstown Campus Addition	1-Apr-2019	Stabilize disturbed soils on SW steep slopes, washouts are overtopping biologs. Left message with Site Contractor to have landscaping/perimeter control established.	Action required.
2017-64	Home Reconstruction: 5019 Knob Hill Road	5-Apr-2019	Disturbed soils partially stabilized with erosion control blankets silt fence and biologs. Silt fence on rear yard has >50% soil deposition and will need sediment removed. Sediment deposited in infiltration basin needs to be removed and basin re-graded. Spoke with Site Contractor, homeowner is planning on completing landscaping.	Action required.

Permit #	Project Name	Date of Inspection	Observations	Status
2017-11	Rize @ Opus Apartment Building, 1010 Bren Road	2-Apr-2019	Building construction in progress. Sections of silt fence and biologs damaged or displaced. Spoke with Site Contractor, will have repairs made within 48 hours.	Action required.
2016-141	Home Construction: 5203 Duncraig Road	5-Apr-2019	Disturbed soil steep slopes need stabilization as soil washouts are occurring on both sides of property. Left message with Site Contractor contact.	Action required.
2016-93	Gateway Pointe. SE Quad—York Avenue and West 66th Street	4-Apr-2019	Building construction in progress. Damaged/displaced biologs need to be replaced and sediment washouts and tracking to streets needs to be removed. Left message with On-Site Contractor.	Action required.
2016-72	Braemar Cold Storage Site Storage Improvements—7600 Braemar Boulevard	4-Apr-2019	Steep slope vegetation not fully established. Several washout gullies appear to be forming.	Concerns noted for follow-up
2016-05	Edina High School Redevelopment—6754 Valley View Road	5-Apr-2019	Several sloped sections on east side of site has sparse vegetation and some washouts forming. Landscaping repairs are scheduled according to school staff.	Action required.