

resourceful. naturally. engineering and environmental consultants

To: Nine Mile Creek Watershed District—File

From: Kim Johannessen

Subject: October1 through October5, 2018—Erosion Inspection

Date: October 10, 2018

Project: 23/27-003 JDD 007

Barr staff has inspected construction sites in the Nine Mile Creek Watershed District for conformance to erosion and sediment control policies. Listed below are construction projects and the improvement needed for effective erosion control. The sites were inspected from October 1 to October 5, 2018.

Site Inspections

| 2018-98 | CenterPoint Energy Utility Installation: Wilyran Avenue and 66 th Street Project | October 5, 2018 |
|---------|---|-----------------|
| | Utility construction in progress. No project issues. | |
| 2018-95 | CenterPoint Energy Utility Installation: St. John's Avenue Project | October 5, 2018 |
| | Utility construction in progress along project. Inlet protection installed in impacted areas. | |
| 2018-94 | CenterPoint Energy Utility Installation: Emerson Project | October 1, 2018 |
| | Construction not started. Utility locates marked. | |
| 2018-93 | Home Construction: 6334 Coteau Trail | October 2, 2018 |
| | No current construction activity. Perimeter silt fence and biologs repaired/replaced. | |
| 2018-92 | CenterPoint Energy Utility Installation: 86 th Penn to Xerxes Project | October 1, 2018 |
| | Utility construction in progress along small sections of project site. No issues observed. | |
| 2018-88 | Home Construction: 6412 Indian Hills Rd. | October 4, 2018 |
| | Home construction in progress. Perimeter silt fence, biologs, and existing construction entrance in place. No current issues. | |
| 2018-87 | Home Construction: 5601 Tracy Avenue | October 5, 2018 |
| | Construction not started. | |

| 2018-86 | Home Construction: 6005 Pine Grove Road | October 4, 2018 |
|---------|--|-----------------|
| | Home construction in progress. Perimeter silt fence and biologs in place. | |
| | Rock construction entrance needs improvement. | |
| | Left message with Site Contractor | |
| 2018-85 | Centennial Lakes Park Pedestrian Trail and Bridge | October 4, 2018 |
| | Bridge construction in progress. Perimeter BMPs installed along project and soil stockpiles to project issues observed. | |
| 2018-84 | Parking Lot Improvements: 5215 Edina Industrial Boulevard | October 3, 2018 |
| | Construction not started. | |
| 2018-83 | Meadow Creek Condos Watermain Replacement: 823 Old Settlers Trail | October 2, 2018 |
| | Construction not started. | |
| 2018-82 | Home Construction: 6608 Cahill Road | October 5, 2018 |
| | Home construction in progress. Existing concrete driveway for construction entrance. | |
| | Perimeter biologs in place might be insufficient protection for large on- site soil stockpiles. | |
| 2018-81 | All Saints Lutheran Church Parking Lot Improvements: 15915 Excelsior | October 2, 2018 |
| | Parking lot construction appears complete. Curb installed. Parking areas paved. Disturbed soils graded. Landscaping in progress. | |
| 2018-80 | Interchange Improvements: TH 62/France Avenue | October 5, 2018 |
| | Construction not started. | |
| 2018-78 | Garage Addition: 5300 Dundee Road | October 5, 2018 |
| | Garage construction in progress. BMPs in place. No project issues. | |
| 2018-77 | Home Construction: 9020 West Bush Lake Road | October 3, 2018 |
| | Home construction in progress. Perimeter silt fence, biologs, and construction entrance in place. No current project issues. | |
| 2018-76 | Victoria Pond Maintenance: 4801 West 81 st and 4851 American Boulevard | October 3, 2018 |
| | No current construction activity. | |
| 2018-74 | Bloomington Senior Housing: 6701 West 78th Street | October 3, 2018 |
| | Construction not started. | |
| | | |

| 2018-73 | CenterPoint Energy Utili | ty Installation, Countryside Rd: | October 5, 2018 |
|---------|------------------------------|---|-----------------|
| | Utility construction in prog | gress. No project issues observed. | |
| 2018-71 | Home Construction: 310 | 0 West 98 th Street | October 1, 2018 |
| | | gress. Perimeter silt fence and rock good condition. No current issues. | |
| 2018-70 | Mill & Overlay: 4200 We | est 76 th Street | October 4, 2018 |
| | No construction activity. | | |
| 2018-68 | Knox and American Buil | ding Demolition | October 1, 2018 |
| | | ng in progress. On-site soil stockpiles BMPs. Inlet protection in place. No current | |
| 2018-65 | Sidewalk Construction | | October 3, 2018 |
| | Prairie Center Drive | Sidewalk construction and landscaping restored. | |
| | | Project will be removed from inspection list. | |
| | Prairie Lakes Drive | Sidewalk construction and landscaping restored. | |
| | | Project will be removed from inspection list. | |
| | Anderson Lakes Parkway | Sidewalk construction and landscaping complete. | |
| | | Project will be removed from inspection list. | |
| | Anderson Way | Sidewalk construction and landscaping complete. | |
| | | Project will be removed from inspection list. | |
| 2018-64 | Sidewalk Construction: \ | /alley View Road | October 3, 2018 |
| | Sidewalk construction and | vegetation restored. | |
| | Project will be removed fro | om inspection list. | |
| 2018-63 | Home Reconstruction: 6 | 633 Parkwood Road | October 4, 2018 |
| | - | te. Site surveying in progress. Perimeter silt driveway in place. No current project | |
| 2018-62 | Home Addition: 8272 Ye | ork Avenue | October 1, 2018 |
| | Home construction in pro | gress. | |
| | Damaged perimeter silt fe | nce near soil stockpile needs repair. | |
| | Left message with Site C | ontractor. | |

| 2018-61 | Kidde Academy: 7711 Computer Avenue | October 4, 2018 |
|---------|--|-----------------|
| | Site and pond vegetation not fully established. No erosion-related issues observed. After recent heavy rainfall, remaining biologs can be removed from site. | |
| 2018-60 | Home Addition: 5127 Skyline Drive | October 5, 2018 |
| | Home construction in progress. Perimeter BMPs in place. | |
| | Minor tracking to street cleaned at end of the day. No current project issues. | |
| 2018-59 | Solbekken Villas, 5740-5750 Shady Oak Rd. | October 2, 2018 |
| | No current construction activity. Roll-off container on site. No BMPs installed. BMPs will need to be installed before construction begins. | |
| 2018-58 | Pool Construction: 7710 Marth Court | October 3, 2018 |
| | No construction activity. | |
| 2018-57 | Home Addition: 8641 Kell Avenue South | October 1, 2018 |
| | Construction not started. | |
| 2018-56 | Budget Truck Rental: 305 American Blvd. | October 1, 2018 |
| | Building and parking lot construction in progress. | |
| | Sections of silt fence and biologs damaged or missing. | |
| | Sediment washouts tracked to street. | |
| | Left message with Contractor to have BMPs replaced and streets cleaned. | |
| 2018-54 | Home Addition: 6612 Cornelia Drive | October 5, 2018 |
| | Home construction in progress. Damaged silt fence in rear yard backed up with additional biologs. Inlet protection and construction in place. | |
| 2018-53 | Home Construction: 5130 Ridge Trail | October 4, 2018 |
| | Home construction in progress. Perimeter fence, biologs, inlet protection, and rock construction entrance in good condition. No project issues observed. | |
| 2018-51 | Bloomington Mill & Overlay: 78 th Street Area | October 4, 2018 |
| | No current construction activity. Utility locates marked on street. | |
| 2018-50 | Bloomington Mill & Overlay: Brookside Area | October 1, 2018 |
| | Street construction complete. Disturbed soil landscaping in progress. No current project issues. | |

| 2018-49 | NE Penn Stormwater Storage Project | October 1, 2018 |
|---------|--|-----------------|
| | Site excavation and tracking construction in progress. Perimeter biologs, inlet protection, and construction entrance in place. No current site issues. | |
| 2018-47 | Woodhill Road Reconstruction | October 2, 2018 |
| | Street construction in progress. Curb installed and partially paved on north and south sections. Excavation in progress along middle section. Perimeter silt fence, biologs, and inlet protection in place. No project issues observed. | |
| 2018-46 | Home Addition: 5300 West 61 st Street | October 5, 2018 |
| | Home construction in progress. Perimeter silt fence, biologs, and construction in place. | |
| 2018-45 | CenterPoint Energy: Griffit Street Replacement | October 4, 2018 |
| | Utility construction complete. | |
| | Project will be removed from inspection list. | |
| 2018-44 | CenterPoint Energy: MBLSE Nicollet Project | October 1, 2018 |
| | Utility construction in progress. Inlet protection in place. Perimeter BMPs in place on soil stockpiles. No project issues. | |
| 2018-43 | Home Reconstruction: 6237 Knoll Drive | October 4, 2018 |
| | Home construction in progress. Perimeter silt fence, biologs, and existing asphalt driveway in place. | |
| 2018-42 | Drury Hotel: Bloomington | October 4, 2018 |
| | Site excavation and grading in progress. Perimeter silt fence, biologs, inlet protection, and rock construction in good condition. Trucks hauling in rock and removing soil. No project issues observed. | |
| 2018-41 | Acorn Mini Storage: Bloomington | October 1, 2018 |
| | Existing parking lot asphalt removal in progress. Perimeter biologs, inlet protection, and asphalt construction entrance in place. No project issues. | |
| 2018-40 | Glen Lake Elementary Parking Lot Construction | October 2, 2018 |
| | Parking lot construction and landscaping complete. | |
| | Project will be removed from inspection list. | |
| 2018-39 | Mill & Overlay: 11 th Avenue South | October 2, 2018 |
| | Street construction in progress. No project issues observed. | |
| | | |

| 2018-38 | Home Additional: 6301 Westwood Ct. | October 4, 2018 |
|---------|--|-----------------|
| | Home construction and driveway installation in progress. Perimeter silt fence and biologs in place. No project issues. | |
| 2018-37 | Home Construction: 6104 Westridge Boulevard | October 5, 2018 |
| | Home construction and landscaping in progress. Perimeter BMPs and construction entrance in place. No project issues. | |
| 2018-36 | Street Improvements: 108 th Street | October 1, 2018 |
| | Street construction complete. Site vegetation not fully established. | |
| 2018-35 | James Avenue | October 1, 2018 |
| | Traffic barricades in place. No current construction activity. | |
| 2018-34 | 86 th Street | October 1, 2018 |
| | Street construction in progress. Curb installed. Streets partially paved. Small soil piles along project will need perimeter BMPs if left greater | |
| | than 24 hours. | |
| 2018-33 | Girard Avenue | October 1, 2018 |
| | Street construction and restoration complete. | |
| | Project will be removed from inspection list. | |
| 2018-29 | McDonald's Parking Lot Improvements | October 4, 2018 |
| | Parking lot construction and site restoration complete. | |
| | Project will be removed from inspection list. | |
| 2018-28 | Edina Street Mill and Overlay Projects | |
| | a) Presidents C: | October 4, 2018 |
| | Project complete. | |
| | b) Presidents D: | Sept. 6, 2018 |
| | Project complete. | |
| | c) Fox Meadow: | |
| | Project complete. | |
| | d) Countryside C: | October 5, 2018 |
| | Street construction in progress. No project issues observed. | |
| | e) Indian Hills D: | |
| | Project complete. | |

| | f) | Valley View Rd: | |
|--------|---------|--|-----------------|
| | ') | Project complete. | |
| | | | October E 2018 |
| | g) | West 66 th St: | October 5, 2018 |
| | | Street construction appears complete. No project issues. | |
| | h) | Braemar Hills D: | October 3, 2018 |
| | | Sections of street paved. No current issues. | |
| | i) | West 70 th Street: | October 3, 2018 |
| | | Sections of 70 th Street paved. No current issues. | |
| | j) | Cahill Road: | October 3, 2018 |
| | | Street construction and restoration complete. | |
| | | Project will be removed from inspection list. | |
| | k) | Cahill A: | October 3, 2018 |
| | | Street construction and restoration complete. | |
| | | Project will be removed from inspection list. | |
| | I) | Bush Lake Road: | October 3, 2018 |
| | | Street construction and restoration complete. | |
| | | Project will be removed from inspection list. | |
| | m) | Edina Industrial/Normandale: | October 3, 2018 |
| | | Street construction appears complete. | |
| | n) | Normandale Rd/Pentagon: | October 4, 2018 |
| | | Street construction not started. Utility locates marked on street. | |
| | o) | Edinborough A & B: | October 4, 2018 |
| | | Construction not started. Utility locates marked on street. | |
| 18-27 | Home | Construction: 6453 McCauley Terrace | October 4, 2018 |
| | | construction in progress. Biologs installed along damaged silt Fracked sediment removed from street. | |
|)18-26 | Home | Construction: 5616 70 th Street West | October 3, 2018 |
| | | construction in progress. Perimeter BMPs in place. Tracked nt removed from street. No project issues. | |
|)18-25 | I-35W | Noisewall Repair: I-494 to West 106 th Street | October 1, 2018 |
| | Project | vegetation restoration not fully established. | |
| | 5 | - · | |

| 2018-24 | Westbrook Park Pickleball Court | October 1, 2018 |
|---------|--|-----------------|
| _ | Court construction complete. Site vegetation not fully established. | |
| 2018-23 | 69 th Street Roundabout Construction | October 4, 2018 |
| _ | Sidewalk construction in progress. No project issues observed. | |
| 2018-22 | Edina Promenade | October 4, 2018 |
| | Construction/demolition not started. | |
| 2018-21 | Normandale D/Bredesen A: Street Reconstruction | October 5, 2018 |
| | Street construction appears complete. No project issues. | |
| 2018-20 | Normandale Community College Parking Lot Improvements | October 5, 2018 |
| | Parking lot construction complete. Site vegetation not fully established. No current project issues. | |
| 2018-19 | Central Park Pickleball Courts | October 2, 2018 |
| | Landscaping activities in progress. Existing vegetation not fully established. | |
| 2018-18 | Normandale Community College, Tunnel and Courtyard Improvements | October 1, 2018 |
| | No current construction activity. | |
| 2018-14 | Pillsbury Truck Storage: 8100 Pillsbury Avenue South | October 1, 2018 |
| | Parking lot construction in progress. No project issues. | |
| 2018-13 | Home Construction: 4501 Dunham Drive | October 5, 2018 |
| | Home construction in progress. | |
| | Damaged silt fence adjacent to soil stockpile/street needs repair. | |
| | Left message with Contractor. | |
| 2018-12 | Home Construction: 5111 Bluff Circle | October 4, 2018 |
| | Home construction in progress. Perimeter silt fence and construction entrance repaired. Inlet protection in place. | |
| | Minor sediment tracking to street. | |
| 2018-10 | Friendship Village: SE Quad of 169 & 494 | October 3, 2018 |
| | Construction not started. | |
| 2018-08 | Home Construction: 6700 Point Drive | October 5, 2018 |
| | Building construction in progress. Perimeter silt fence, biologs, inlet protection, and construction entrance in place. No project issues. | |

| 2018-07 | Bloomington Self Storage: 9601 Penn Avenue South | October 1, 2018 |
|----------|--|-----------------|
| | Building construction in progress. Perimeter slit fence, biologs, inlet protection, and construction entrance in place. No current project issues. | |
| 2018-06 | Home Construction: 5221 Meadow Road | October 5, 2018 |
| | Construction not started. | |
| 2018-05 | Caribou Coffee and Einstein Bagels: 5000 Vernon Avenue | October 5, 2018 |
| | Building construction in progress. Perimeter silt fence, biologs, inlet protection, and rock construction entrances in place. No current project issues. | |
| 2018-04 | Home Construction: 6005 St. Johns Avenue | October 5, 2018 |
| | Home construction and landscaping complete. | |
| | Project will be removed from inspection list. | |
| 2018-03 | Home Construction: 5504 Cahill Lane | October 5, 2018 |
| | Home construction and landscaping complete. | |
| | Project will be removed from inspection list. | |
| 2018-02 | T.H. 7 Repairs: Baker Road to Louisiana Avenue | October 2, 2018 |
| | Site disturbed soils graded and seeded. No project erosion-related issues observed. | |
| 2018-01 | Home Construction: 6613 Parkwood Road | October 4, 2018 |
| | Home construction in progress. Perimeter silt fence, biologs, and construction in good condition. No project issues. | |
| 2017-132 | T.H. 62 Mill and Overlay: Beach Road to Tracy Avenue | Sept. 6, 2018 |
| | T.H. 62 construction in progress on exit/entrance ramps. Some sections have curb installed and overlay complete. No project erosion-related issues observed. | |
| 2017-131 | T.H. 494 Concrete Barrier: East and West Bush Lake Road | October 3, 2018 |
| | Road construction and barrier wall construction in progress. BMPs in place. No current erosion-related issues observed. | |
| 2017-129 | Hopkins Pavilion 2018 Improvements: 11000 Excelsior Boulevard | October 2, 2018 |
| | Building construction and landscaping appear complete. Site vegetation not fully established. Inlet protection Inlet protection and biologs remain in place. | |

| 2017-128 | Bridge Reconstruction: I-35W-Cliff Road to 106 th Avenue | October 1, 2018 |
|----------|--|-----------------|
| | Bridge and ramp construction in progress. Jersey wall with fabric backing in place providing erosion protection from high river water level. Perimeter silt fence, ditch checks in good condition. Disturbed soils blanketed or hydro-mulched. No erosion-related issues observed. | |
| 2017-125 | American Boulevard Storage and Grading | October 1, 2018 |
| | Site excavation and grading in progress. Perimeter silt fence, biologs, inlet protection, and construction entrance in place. No current project erosion-related issues observed. | |
| 2017-124 | Home Construction: 5316 Dundee Road | October 5, 2018 |
| | Home construction complete and driveway installed. Disturbed soils graded and leveled but recent heavy rain events created washout channels. Perimeter biologs captured majority of sediment. | |
| 2017-120 | Creek Valley Elementary School Building Addition: 6401 Gleason Road | October 4, 2018 |
| | Building construction and landscaping appears complete. No project issues. | |
| 2017-116 | Concierge Apartment Parking Expansion: 7620 Penn Avenue South | October 4, 2018 |
| | No current construction activity. | |
| 2017-114 | House Demolition: 5200 Dundee Road | October 5, 2018 |
| | Foundation excavation in progress. Large soil stockpiles on site. Perimeter silt fence, biologs, and existing driveway in place for construction entrance. No project issues. | |
| 2017-113 | Home Addition: 6116 Eden Prairie Road | October 5, 2018 |
| | Home construction in progress. No project issues observed. | |
| 2017-111 | Willow Creek Road Embankment Repair: 7030 Willow Creek Road | October 2, 2018 |
| | Site vegetation established. | |
| | Project will be removed from inspection list. | |
| 2017-110 | Southdale Shake Shack: SE Corner, West 66 th and France | October 4, 2018 |
| | Building construction and landscaping in progress. Perimeter BMPs in place. No project issues. | |
| 2017-109 | JC Penney Redevelopment: 200 Southdale Center | October 4, 2018 |
| | Building construction in progress. | |

| 2017-108 | Andy's Truck Storage Parking Lot Reconstruction: 8116 Pillsbury Avenue | October 1, 2018 |
|----------|---|-----------------|
| | Silt fence in place. Construction not started. | |
| 2017-107 | Emanuelson Podas Parking Lot Modification: 7705 Bush Lake Road | October 1, 2018 |
| | Parking lot construction and restoration complete. | |
| | Project will be removed from inspection list. | |
| 2017-106 | Site Grading: 9431 Garfield Avenue | October 1, 2018 |
| | Site perimeter BMPs removed. Erosion control blanket vegetation density <20% established. | |
| 2017-105 | Home Construction: 5144 Ridge Trail | October 4, 2018 |
| | Home construction complete. Site landscaping in progress. Perimeter biologs in place. No current project issues. | |
| 2017-104 | Bloomington Care Center Parking Lot Expansion | October 1, 2018 |
| | Construction not started. | |
| 2017-102 | Home Construction: 6616 Indian Hills Circle | October 4, 2018 |
| | Home construction and landscaping complete. Site vegetation not fully established. Perimeter biologs remain in place. | |
| 2017-101 | Girard Lake Culvert Replacement: 8401 France Avenue South | October 4, 2018 |
| | No construction activity. | |
| 2017-100 | Bus Barn Site: 5150 Brookside and 5220 Eden Avenues | October 5, 2018 |
| | Building construction in progress. Contractor in process of cleaning sediment from inlet basin. Additional inlet protection will be installed on downstream location and sediment delta will be removed and maintained. | |
| 2017-98 | Home Construction: 5105 Mirror Lake Drive | October 5, 2018 |
| | Home construction in progress. Perimeter silt fence biologs and construction entrance in place. No site issues. | |
| 2017-95 | Home Construction: 5204 61 st Street West | October 5, 2018 |
| | Home construction in progress. Driveway installed Perimeter BMPs in place. No project issues. | |
| 2017-94 | River Valley Crosstown Campus Addition | October 2, 2108 |
| | Inlet protection maintained and sediment removed from parking areas. Perimeter biologs installed around on-site soil/gravel stockpiles No current project issues. | |

| 2017-93 | Budget Truck Rental: 305 American Boulevard | October 1, 2018 |
|--------------------|---|-----------------|
| | Building and parking lot construction in progress. | |
| | Sections of silt fence and biologs damaged or missing. | |
| | Sediment tracked and washed to street. | |
| | Left message with Contractor to have repairs and street cleaned. | |
| 2017-92 | Valley View Road Trail Expansion | October 2, 2018 |
| | Trail construction and grading in progress. No current project issues observed. | |
| 2017-88 | Nine Mile Creek Regional Spur Trails, A & B | October 5, 2018 |
| | Vegetation along project not fully established. No current issues observed. | |
| 2017-79 | Lone Lake Park Pickleball Courts | October 2, 2018 |
| | Additional BMPs were installed to prevent washouts along paved hiking trail. Disturbed soils impacted by recent heavy rainfall were covered by erosion control blankets. No project erosion-related issues observed. | |
| | | |
| 2017-77 | Bloomington Storm Sewer Maintenance: North Myr Marsh | |
| 2017-77 | Bloomington Storm Sewer Maintenance: North Myr Marsh A. Construction not started. | October 1, 2018 |
| 2017-77 | | October 1, 2018 |
| 2017-77 | A. Construction not started. | October 1, 2018 |
| 2017-77 | A. Construction not started. B. Project complete. | October 1, 2018 |
| 2017-77 | A. Construction not started. B. Project complete. C. Project complete. | October 1, 2018 |
| 2017-77 | A. Construction not started. B. Project complete. C. Project complete. D. Project complete. | October 1, 2018 |
| 2017-77 | A. Construction not started. B. Project complete. C. Project complete. D. Project complete. E. Project complete. | October 1, 2018 |
| 2017-77 | A. Construction not started. B. Project complete. C. Project complete. D. Project complete. E. Project complete. F. Project complete. | October 1, 2018 |
| 2017-77 2017-74 | A. Construction not started. B. Project complete. C. Project complete. D. Project complete. E. Project complete. F. Project complete. G. Project complete. | October 1, 2018 |
| | A. Construction not started. B. Project complete. C. Project complete. D. Project complete. E. Project complete. F. Project complete. G. Project complete. H. Project complete. | |
| | A. Construction not started. B. Project complete. C. Project complete. D. Project complete. E. Project complete. F. Project complete. G. Project complete. H. Project complete. Home Reconstruction: 5809 South Drive Home construction in progress. Perimeter BMPs and rock | |

| 2017-64 | Home Reconstruction: 5019 Knob Hill Road Octo | |
|---------|---|-----------------|
| | Erosion control blankets recently installed on steep slopes. Perimeter silt fence repaired and inlet protection. Cleaned in street. | |
| | Blankets were installed over washout gullies without site grading, erosion will likely continue under blankets. | |
| | Secondary silt fence was repaired but 1 st silt fence is still undermined at base of steep slope. Holding pond was partially filled with sediment and will need repairs. | |
| | Remove sediment washed into wetland. | |
| | Left message with Contractor. | |
| 2017-61 | Wentworth Storage Lot: 8824-8870 Wentworth Avenue South | October 1, 2018 |
| | Construction not started. Security fence installed around project site. | |
| 2017-59 | Edina Mill and Overlay | October 4, 2018 |
| | Valley View Road: | |
| | West 66th Street: Street, curb, and sidewalk construction complete. Site restored. <i>Project will be removed from inspection list</i> . | October 4, 2018 |
| 2017-55 | Home Reconstruction: 6209 Crest Lane | October 5, 2018 |
| | Home construction and driveway installation complete. Landscaping in progress. Perimeter BMPs remain place. | |
| 2017-50 | Home Reconstruction: 5630 Glen Avenue | October 2, 2018 |
| | Landscaping in progress. No current project issues. | |
| 2017-46 | 66 th Street and York Ave. Street Improvements | October 4, 2018 |
| | Street construction complete and site restored. | |
| | Project will be removed from inspection list. | |
| 2017-45 | Alaskan Fur Parking Lot Expansion, 7800 Normandale Blvd. | October 3, 2018 |
| | Infiltration basin nearly at capacity from recent heavy rainfall. No erosion-related issues observed. | |
| 2017-43 | Double Tree Hotel Parking Lot Expansion, 7800 Normandale Blvd. | October 3, 2018 |
| | Infiltration basin nearly at capacity from recent heavy rainfall. No erosion-related issues observed. | |
| 2017-29 | 2017-102 PMP Street Maintenance Project, Mill & Overlay: East 86 th Street | |

| 2017-28 | Hennepin County South Suburban Court Relocation, 1800 Old Shakopee Rd. | October 1, 2018 | |
|---------|--|-----------------|--|
| | Construction not started. | | |
| 2017-27 | I-35W and West 86 th Street Bridge Replacement | October 1, 2018 | |
| | Slope blanketed vegetation not fully established. No project erosion- related issues observed. | | |
| 2017-26 | Home Construction: 5124 West 60 th Street | October 5, 2018 | |
| | Home construction in progress. Driveway installed. Perimeter silt fence and biologs in place. No project issues. | | |
| 2017-19 | Christ Presbyterian Church Addition | October 5, 2018 | |
| | Construction and landscaping in progress. No project issues. | | |
| 2017-18 | I-494 and East Bush Lake Road: Road and Bridge Construction | October 3, 2018 | |
| | Bridge and ramp construction in progress. | | |
| | Several on-site soil stockpiles need perimeter BMP protection installed. | | |
| | Left message with onsite Contractor. | | |
| 2017-16 | Home Reconstruction: 6608-6612 Indian Hills Rd. | October 4, 2018 | |
| | Home construction complete. Landscaping in progress. Perimeter silt fence remains on site. | | |
| 2017-13 | 2017 Hopkins Street and Utility Projects | October 2, 2018 | |
| | 5 th Avenue/7 th Street: Former staging area at 5 th and 7 th Street in process of additional grading and seeding. | | |
| | 2 nd Street Areas: | | |
| 2017-11 | Rize @ Opus Apartment Building, 1010 Bren Road | October 2, 2018 | |
| | Building construction in progress. Perimeter dual silt fence, biologs, inlet protection, and construction entrance in good condition. No current site issues observed. | | |
| 2017-10 | Peace Lutheran Church | October 3, 2018 | |
| | Several sections of disturbed soils vegetation not established. No erosion issues observed. | | |
| 2017-09 | Baker Road Mini Storage | October 2, 2018 | |
| | Pond and slope vegetation not fully established. Sections of silt fence remain along west side of site. | | |

| 2017-08 | Pump and Meter Building Addition, 11303 Excelsior Blvd. | October 2, 2018 |
|----------|--|-----------------|
| | No current construction activity. | |
| 2016-143 | Cornelia Elementary School Addition: 7000 Cornelia Drive | |
| | | |
| 2016-142 | International Spanish Language Academy Redevelopment, 5959 Shady Oak Rd. | October 2, 2018 |
| | Construction not started. | |
| 2016-141 | Home Construction: 5203 Duncraig Road | October 5, 2018 |
| | Home construction and driveway complete. | |
| | Erosion and washouts occurring on steep slopes on both sides of property. Disturbed soils need to be stabilized/vegetated. | |
| | Remove sediment washouts to wetland. | |
| | Left message with Contractor. | |
| 2016-134 | #52643 Edina Small Cell Fiber Optic Line Installation | October 3, 2018 |
| | No construction activity. | |
| 2016-130 | Home Reconstruction: 5812 Hidden Lane | October 5, 2018 |
| | Construction not started. | |
| 2016-129 | Carlson Print Parking Lot Expansion, 7490 Golden Triangle | October 5, 2018 |
| | Site vegetation not fully established. | |
| 2016-119 | Braemar Golf Course Renovation | October 4, 2018 |
| | Home construction in progress. | |
| | Perimeter silt fence and biologs in place. | |
| | Rock construction will need to be improved. | |
| | Left message with on-site Contractor. | |
| 2016-112 | Street Maintenance Projects (103-112) | |
| 2016-111 | Street Maintenance Projects (103-112) | |
| 2010 111 | | |
| 2016-109 | Street Maintenance Projects (103-112) | |
| 2016-107 | Street Maintenance Projects (103-112) | |
| | | |

| 2016-105 Street Maintenance Projects (103-112) 2016-104 Street Maintenance Projects (103-112) 2016-103 Street Maintenance Projects (103-112) 2016-101 Home Construction—6005 Pine Grove Road October 4, 2018 Home construction in progress. Perimeter silt fence and biologs in place. October 4, 2018 Rock construction will need to be improved. Left message with on-site Contractor. 2016-100 Williston Woods Development, Williston Rd. and Excelsior Blvd. October 2, 2018 Home construction in progress at both locations. Perimeter silt fence, biologs, inlet protection, and construction in place. No current project issues. October 2, 2018 2016-99 S901 Lincoln Drive Residences October 3, 2018 Vegetation not fully established along sections of site. No project-related issues observed. October 3, 2018 2016-97 Cahill Storage—7625 Cahill Road October 3, 2018 Construction not started. October 4, 2018 2016-93 Gateway Pointe. SE Quad—York Avenue and West 66 th Street October 4, 2018 Building construction in progress. Perimeter silt fence, biologs, inlet protection, and rock construction entrance in good condition. No project issues observed. October 2, 2018 2016-93 Gateway Pointe. SE Quad—York Avenue and West 66 th Street Oc | 2016-106 | Street Maintenance Projects (103-112) | |
|--|----------|--|-----------------|
| 2016-103Street Maintenance Projects (103-112)2016-101Home Construction—6005 Pine Grove Road Home construction in progress. Perimeter silt fence and biologs in place. Rock construction will need to be improved. Left message with on-site Contractor.October 4, 20182016-100Williston Woods Development, Williston Rd. and Excelsior Blvd. Home construction in progress at both locations. Perimeter silt fence, biologs, inlet protection, and construction in place. No current project issues.October 2, 20182016-995901 Lincoln Drive Residences Vegetation not fully established along sections of site. No project- related issues observed.October 3, 2018 Construction not started.2016-97Cahill Storage—7625 Cahill Road Building construction in progress. Perimeter silt fence, biologs, inlet protection, and rock construction entrance in good condition. No project issues observed.October 4, 2018 Cotober 4, 2018 Cotober 2, 20182016-93Camp Edenwood Respite Cabin Pond vegetation nearly established. Silt fence at pond base should be removed.October 2, 2018 Cotober 2, 20182016-85Verizon Telecommunications Tower construction, 6752 Shady Oak Rd.October 2, 2018 Cotober 2, 2018 | 2016-105 | Street Maintenance Projects (103-112) | |
| 2016-101Home Construction—6005 Pine Grove Road Home construction in progress. Perimeter silt fence and biologs in place. Rock construction will need to be improved. Left message with on-site Contractor.October 4, 20182016-100Williston Woods Development, Williston Rd. and Excelsior Blvd. Home construction in progress at both locations. Perimeter silt fence, biologs, inlet protection, and construction in place. No current project issues.October 2, 20182016-995901 Lincoln Drive Residences Vegetation not fully established along sections of site. No project- related issues observed.October 3, 20182016-97Cahill Storage—7625 Cahill Road Construction in progress. Perimeter silt fence, biologs, inlet protection, and rock construction entrance in good condition. No project issues observed.October 4, 20182016-93Gateway Pointe. SE Quad—York Avenue and West 66th Street Pond vegetation nearly established. Silt fence at pond base should be removed.October 2, 20182016-85Verizon Telecommunications Tower construction, 6752 Shady Oak Rd.October 2, 2018 | 2016-104 | Street Maintenance Projects (103-112) | |
| Home construction in progress. Perimeter silt fence and biologs in place. Rock construction will need to be improved. Left message with on-site Contractor.October 2, 20182016-100Williston Woods Development, Williston Rd. and Excelsior Blvd. Home construction in progress at both locations. Perimeter silt fence, biologs, inlet protection, and construction in place. No current project issues.October 2, 20182016-995901 Lincoln Drive Residences Vegetation not fully established along sections of site. No project- related issues observed.October 3, 20182016-97Cahill Storage—7625 Cahill Road Construction not started.October 4, 20182016-93Gateway Pointe. SE Quad—York Avenue and West 66th Street protection, and rock construction entrance in good condition. No project issues observed.October 2, 20182016-89Camp Edenwood Respite Cabin Pond vegetation nearly established. Silt fence at pond base should be removed.October 2, 20182016-85Verizon Telecommunications Tower construction, 6752 Shady Oak Rd.October 2, 2018 | 2016-103 | Street Maintenance Projects (103-112) | |
| place. Rock construction will need to be improved. Left message with on-site Contractor.October 2, 20182016-100Williston Woods Development, Williston Rd. and Excelsior Blvd. Home construction in progress at both locations. Perimeter silt fence, biologs, inlet protection, and construction in place. No current project issues.October 2, 20182016-995901 Lincoln Drive Residences Vegetation not fully established along sections of site. No project- related issues observed.October 3, 20182016-97Cahill Storage—7625 Cahill Road Construction not started.October 3, 20182016-93Gateway Pointe. SE Quad—York Avenue and West 66th Street protection, and rock construction entrance in good condition. No project issues observed.October 2, 20182016-89Camp Edenwood Respite Cabin Pond vegetation nearly established. Silt fence at pond base should be removed.October 2, 20182016-85Verizon Telecommunications Tower construction, 6752 Shady Oak Rd.October 2, 2018 | 2016-101 | Home Construction—6005 Pine Grove Road | October 4, 2018 |
| Left message with on-site Contractor.2016-100Williston Woods Development, Williston Rd. and Excelsior Blvd. Home construction in progress at both locations. Perimeter silt fence, biologs, inlet protection, and construction in place. No current project issues.October 2, 20182016-995901 Lincoln Drive Residences Vegetation not fully established along sections of site. No project- related issues observed.October 3, 20182016-97Cahill Storage—7625 Cahill Road Construction not started.October 3, 20182016-93Gateway Pointe. SE Quad—York Avenue and West 66th Street protection, and rock construction entrance in good condition. No project issues observed.October 2, 20182016-89Camp Edenwood Respite Cabin Pond vegetation nearly established. <i>Sitt fence at pond base should be removed.</i> October 2, 20182016-85Verizon Telecommunications Tower construction, 6752 Shady Oak Rd.October 2, 2018 | | | |
| 2016-100Williston Woods Development, Williston Rd. and Excelsior Blvd. Home construction in progress at both locations. Perimeter silt fence, biologs, inlet protection, and construction in place. No current project issues.October 2, 20182016-995901 Lincoln Drive Residences Vegetation not fully established along sections of site. No project- related issues observed.October 3, 20182016-97Cahill Storage—7625 Cahill Road Construction not started.October 3, 20182016-93Gateway Pointe. SE Quad—York Avenue and West 66th Street protection, and rock construction entrance in good condition. No project issues observed.October 2, 20182016-89Camp Edenwood Respite Cabin Pond vegetation nearly established. Silt fence at pond base should be removed.October 2, 20182016-85Verizon Telecommunications Tower construction, 6752 Shady Oak Rd.October 2, 2018 | | Rock construction will need to be improved. | |
| Home construction in progress at both locations. Perimeter silt fence, biologs, inlet protection, and construction in place. No current project issues.October 2, 20182016-995901 Lincoln Drive Residences Vegetation not fully established along sections of site. No project- related issues observed.October 3, 20182016-97Cahill Storage—7625 Cahill Road Construction not started.October 3, 20182016-93Gateway Pointe. SE Quad—York Avenue and West 66 th Street protection, and rock construction entrance in good condition. No project issues observed.October 2, 20182016-89Camp Edenwood Respite Cabin Silt fence at pond base should be removed.October 2, 20182016-85Verizon Telecommunications Tower construction, 6752 Shady Oak Rd.October 2, 2018 | | Left message with on-site Contractor. | |
| biologs, inlet protection, and construction in place. No current project issues.October 2, 20182016-995901 Lincoln Drive Residences Vegetation not fully established along sections of site. No project- related issues observed.October 3, 20182016-97Cahill Storage—7625 Cahill Road Construction not started.October 3, 20182016-93Gateway Pointe. SE Quad—York Avenue and West 66 th Street Building construction in progress. Perimeter silt fence, biologs, inlet protection, and rock construction entrance in good condition. No project issues observed.October 2, 20182016-89Camp Edenwood Respite Cabin Silt fence at pond base should be removed.October 2, 20182016-85Verizon Telecommunications Tower construction, 6752 Shady Oak Rd.October 2, 2018 | 2016-100 | Williston Woods Development, Williston Rd. and Excelsior Blvd. | October 2, 2018 |
| Vegetation not fully established along sections of site. No project- related issues observed.October 3, 20182016-97Cahill Storage—7625 Cahill Road Construction not started.October 3, 20182016-93Gateway Pointe. SE Quad—York Avenue and West 66th Street Building construction in progress. Perimeter silt fence, biologs, inlet protection, and rock construction entrance in good condition. No project issues observed.October 4, 20182016-89Camp Edenwood Respite Cabin Pond vegetation nearly established. Silt fence at pond base should be removed.October 2, 20182016-85Verizon Telecommunications Tower construction, 6752 Shady Oak Rd.October 2, 2018 | | biologs, inlet protection, and construction in place. No current project | |
| related issues observed.2016-97Cahill Storage—7625 Cahill Road Construction not started.October 3, 2018 October 4, 20182016-93Gateway Pointe. SE Quad—York Avenue and West 66th Street Building construction in progress. Perimeter silt fence, biologs, inlet protection, and rock construction entrance in good condition. No project issues observed.October 4, 20182016-89Camp Edenwood Respite Cabin Pond vegetation nearly established. Silt fence at pond base should be removed.October 2, 20182016-85Verizon Telecommunications Tower construction, 6752 Shady Oak Rd.October 2, 2018 | 2016-99 | 5901 Lincoln Drive Residences | October 2, 2018 |
| Construction not started. October 4, 2018 2016-93 Gateway Pointe. SE Quad—York Avenue and West 66 th Street October 4, 2018 Building construction in progress. Perimeter silt fence, biologs, inlet protection, and rock construction entrance in good condition. No project issues observed. October 2, 2018 2016-89 Camp Edenwood Respite Cabin October 2, 2018 Pond vegetation nearly established. Silt fence at pond base should be removed. October 2, 2018 2016-85 Verizon Telecommunications Tower construction, 6752 Shady Oak Rd. October 2, 2018 | | | |
| 2016-93Gateway Pointe. SE Quad—York Avenue and West 66th StreetOctober 4, 2018Building construction in progress. Perimeter silt fence, biologs, inlet protection, and rock construction entrance in good condition. No project issues observed.October 2, 20182016-89Camp Edenwood Respite Cabin Pond vegetation nearly established. Silt fence at pond base should be removed.October 2, 20182016-85Verizon Telecommunications Tower construction, 6752 Shady Oak Rd.October 2, 2018 | 2016-97 | Cahill Storage—7625 Cahill Road | October 3, 2018 |
| Building construction in progress. Perimeter silt fence, biologs, inlet protection, and rock construction entrance in good condition. No project issues observed. 2016-89 Camp Edenwood Respite Cabin October 2, 2018 Pond vegetation nearly established. Silt fence at pond base should be removed. October 2, 2018 2016-85 Verizon Telecommunications Tower construction, 6752 Shady Oak Rd. October 2, 2018 | | Construction not started. | |
| 2016-89 Camp Edenwood Respite Cabin October 2, 2018 Pond vegetation nearly established. Silt fence at pond base should be removed. 2016-85 Verizon Telecommunications Tower construction, 6752 Shady Oak Rd. October 2, 2018 | 2016-93 | Gateway Pointe. SE Quad—York Avenue and West 66 th Street | October 4, 2018 |
| Pond vegetation nearly established. Silt fence at pond base should be removed. 2016-85 Verizon Telecommunications Tower construction, 6752 Shady Oak Rd. | | protection, and rock construction entrance in good condition. No | |
| Silt fence at pond base should be removed. 2016-85 Verizon Telecommunications Tower construction, 6752 Shady Oak Rd. October 2, 2018 | 2016-89 | Camp Edenwood Respite Cabin | October 2, 2018 |
| 2016-85Verizon Telecommunications Tower construction, 6752 Shady Oak Rd.October 2, 2018 | | Pond vegetation nearly established. | |
| 6752 Shady Oak Rd. | | Silt fence at pond base should be removed. | |
| No current construction activity. | 2016-85 | | October 2, 2018 |
| | | No current construction activity. | |

| 2016-72 | Braemar Cold Storage Site Storage Improvements—7600 Braemar Boulevard | October 3, 2018 |
|---------|---|-----------------|
| | Slope vegetation not fully established. | |
| 2016-71 | Homewood Suites, Hotel—66 th Street and York Avenue (SW Quad) | October 4, 2018 |
| | Building construction and landscaping complete. | |
| | Project will be removed from inspection list. | |
| 2016-43 | Climatech Building Renovation, 6950 Washington Avenue October | |
| | Site vegetation restored. | |
| | Project will be removed from inspection list. | |
| 2016-40 | Highlands Elementary School, 5505 Doncaster Way October | |
| | Building construction and landscaping appears complete. No project issues. | |
| 2016-39 | Home Construction: 6609 Blackfoot Pass | October 4, 2018 |
| | Perimeter silt fence needs repair along disturbed soils and street. | |
| | Left message with site Contractor. | |
| 2016-37 | Two MarketPointe Ramp Expansion, 4700 78 th St. | October 4, 2018 |
| _ | Site vegetation not fully established. | |
| 2016-36 | Normandale Improvements, 9-Mile Creek to Poplar Bridge Rd. | October 3, 2018 |
| | Recently disturbed soils stabilized with hydro seeding. No project- related issues observed. | |
| 2016-20 | Minnetonka Corporate Expanded parking, 5900 Clearwater Dr. | October 2, 2018 |
| | Pond vegetation not fully established. | |
| 2016-17 | CenterPoint Energy, Normandale Boulevard Improvements | October 3, 2018 |
| | Recently disturbed soils stabilized with hydro-seeding. No project- related issues observed. | |
| 2016-05 | Edina High School Redevelopment—6754 Valley View Road | October 5, 2018 |
| | Site vegetation not fully established. No erosion-related issues observed. | |
| 2016-04 | Chief's Towing Parking Lot Reconfiguration— 9604/9608 Humboldt Avenue | October 1, 2018 |
| | Berm slope vegetation not established. | |
| | | |

| 2015-130 | Lupient Chevrolet Parking Lot Reconfiguration— 1601 Southtown Drive | October 1, 2018 | |
|----------|--|-----------------|--|
| | Construction not started. | | |
| 2016-87 | Blake Woods Subdivision | October 4, 2018 | |
| | No current construction activity. Site BMPs in place. | | |
| 2016-86 | Glen Lake Senior House | October 2, 2018 | |
| | Infiltration basin vegetation not fully established. No erosion issues observed. | | |
| 2015-84 | Hyland Hills Ski Jump Improvements | October 3, 2018 | |
| | Pond bank stabilization with erosion control blankets in progress. Biologs installed around pond perimeter. No project issues observed. | | |
| 2015-76 | NAPA Auto Addition—1842 Main Street | October 2, 2018 | |
| | Pond slope vegetation not established. | | |
| | Washouts forming. | | |
| 2015-66 | Double Tree Parking Lot Reconfiguration—7800 Normandale | October 3, 2018 | |
| | Infiltration basin nearly at capacity from recent heavy rainfall. No erosion-related issues observed. | | |
| 2015-53 | Nine Mile Creek Regional Trail-East and West Segments | October 4, 2018 | |
| | Vegetation along project trail not fully established. No current issues observed. | | |
| 2015-29 | New Home Construction—6600 Old Shady Oak Road | October 2, 2018 | |
| | Construction not started. | | |
| 2015-28 | 7101 France Avenue Building C | October 4, 2018 | |
| | Slope vegetation not established. | | |
| 2015-16 | Home Construction—6116 Hansen Road | October 5, 2018 | |
| | No construction activity. | | |
| 2014-98 | Margaret A. Cargill Philanthropies—6889 Rowland Rd. | October 2, 2018 | |
| | Site mostly restored. | | |
| | Project will be removed from inspection list. | | |
| 2014-91 | 6 th Avenue Demolition | October 2, 2018 | |
| | Site vegetation not fully established. | | |

| 2014-87 | Pentagon South Demol and Computer Avenue | October 4, 2018 | |
|---|--|---|-----------------|
| | No current construction a | | |
| 2013-93 | Home Construction-Wil | October 2, 2018 | |
| | No current construction a | | |
| 2012-41 | Carlson Print Parking Lo | October 2, 2018 | |
| | No construction activity. | | |
| 2008-23 | The Enclave at Old Shac | dy Oak | October 2, 2018 |
| | 6300 Montee Dr.: | Site landscaping in progress. Perimeter biologs removed for disturbed soil grading. Sediment removed from street. No current project issues. | |
| | 6276 Montee Dr.: | Home construction in progress. Rock construction entrance improved and sediment removed from street. No current project issues. | |
| | 6268 Montee Dr.: | | |
| | 6232 Coteau Trail: | Not inspected | |
| | 6240 Coteau Trail: | Not inspected. | |
| | 6334 Coteau Trail: | No current construction activity. Existing silt fence and biologs repaired/replaced. | |
| | 6358 Coteau Trail | | |
| | 6331 Bellevue Lane: | No current construction activity. | |
| | 6339 Bellevue Lane: | | |
| 2008-19 (REVISED) | The Luxembourg Apartments | | October 1, 2018 |
| | Site vegetation not fully e | | |
| Inspection Requested by Concerned Citizen | 5324 Blake Road Home Development <i>This is Permit 2016-87</i> | | |

Please contact me at 952.832-2686 or <u>KJohannessen@barr.com</u> if you have questions on the projects listed above or any additional items that need to be addressed for the erosion control inspections.