



MEMO

To: Nine Mile Creek Watershed District Board of Managers

From: Lauren Foley

Date: April 8, 2020

Permit Inspection Report

Summary

Per the Administrator's request, sites inspected were mainly active sites with 5 or more acres of disturbance. The other large fraction was made up of follow up inspections from last month. Due to the transition from work at Discovery Point to home office, fewer inspections were completed than normal. This amount will rise next month as 2020-03 is now in effect.

- Number of inspections: 16
- Number of sites removed: 0
- Number of sites to remain in queue with no issues observed: 11
- Number of sites inspected but project not started: 0
- Number of sites with issues observed: 4

Inspections

Sites with Issue(s) Observed Requiring Follow Up				
Permit Number	Address	Type	Summary of Results	Communication
2018-97	7700 Computer Ave, Edina	Commercial	Downed silt fence on W side not supplanted with other BMP	Inspection report sent to permit holder
2018-113	7800-7850 Dupont Ave S, Bloomington	Commercial	Biologs on Clover Dr nearest BMW are overtopped; inlet protection not installed at corner of Dupont and Clover and inlet protection is falling into inlet and missing bag (north of main entrance on Dupont)	Inspection report sent to applicant
2019-68	Knox Ave and American Blvd W, Bloomington	Commercial	Small spot on E side without erosion BMP, small area but medium risk for release	Inspection report sent to applicant
2019-85	5501-5601 American Blvd W	Multi-family	Area without perimeter control next to construction access on American Blvd; compact construction access closest to parking ramp	Inspection report sent to applicant

Follow Up Inspections on Existing Issues				
Permit Number	Address	Type	Summary of Results	Communication
2019-131	10100 Viking Drive, Eden Prairie	Commercial	Stockpile protected with biologs	None needed
2019-11	6241 Crescent Dr, Edina	SFH	Erosion logs added to front yard	None needed
2019-77	6241 Crescent Dr, Edina	SFH	Erosion logs added to supplement erosion control where silt fence is inadequate	None needed
2016-88	SWLRT 5 th St between K-Tel and 11 th Ave	Linear/Public	Added mid-day sweep to area, looks much cleaner	None needed

2016-88	SWLRT adjacent to Milwaukee St section nearest to Excelsior Blvd, Hopkins	Linear/Public	Erosion control logs fixed for continuity	None needed
---------	---	---------------	---	-------------

Totals

All values are estimates

Approximately 185 open permits with potential for activity

- Approximately 130 with activity
- Approximately 55 without activity