



## MEMO

**To: Nine Mile Creek Watershed District Board of Managers**

**From: Lauren Foley**

**Date: July 8, 2020**

### **Permit Inspection Report**

#### ***Summary***

This month's inspections were started off focusing on Minnetonka, then grew to larger sites throughout the District, especially those recently permitted. There were two inspections by request.

- Number of inspections: 26
- Number of sites removed: 3
- Number of sites to remain in queue with no issues observed: 16
- Number of sites inspected but project not started: 1
- Number of sites with issues observed: 6

## ***Inspections***

<b>Sites with Issue(s) Observed Requiring Follow Up</b>				
<b>Permit Number</b>	<b>Address</b>	<b>Type</b>	<b>Summary of Results</b>	<b>Communication</b>
2018-59	5740-5750 Shady Oak Rd, Minnetonka	Multi-Family Housing	Needs inlet protection installed southeast side of property	Inspection report sent to permit holder
2020-33	Nonprofit (church) BMP project: 2200 West Old Shakopee Rd, Bloomington	Comm/NP	Eroding sides of raingarden and mulch for stabilization displaced (per Barr inspector)	Handled by project team
2020-34	Nonprofit (church) BMP project: 9401 Nesbitt Ave, Bloomington	Comm/NP	Eroding sides of raingarden and mulch for stabilization displaced (per Barr inspector)	Handled by project team
2020-35	Nonprofit (church) BMP project: 1701 West Old Shakopee Rd, Bloomington	Comm/NP	Eroding sides of raingarden and mulch for stabilization displaced (per Barr inspector)	Handled by project team

## ***Totals***

\*All values are estimates\*

Approximately 217 open permits with potential for activity

- Approximately 130 with activity
- Approximately 87 without activity