



MEMO

To: Nine Mile Creek Watershed District Board of Managers

From: Lauren Foley

Date: Jan 13, 2020

Permit Inspection Report

Summary

This month's inspections aimed ones from later 2020 that have not yet been inspected, and those in the vicinity for efficiency.

- Number of inspections: 21
- Number of sites removed: 2
- Number of sites to remain in queue with no issues observed: 9
- Number of follow up inspections: 1
- Number of projects hidden excessively under snow: 3
- Number of inspections with project not started: 4
- Number of inspections with issues observed: 2

Inspections

Sites with Issue(s) Observed				
Permit Number	Address	Type	Summary of Results	Communication
2018-48	5517-5525 Eden Prairie Rd, Minnetonka	Subdivision	Missing silt fence (or other perimeter protection) around a very large stockpile – see follow-up table below	Inspection report sent to permit contact
2020-125	6109 Blake Cir, Edina	Single family home	Missing rock on construction access	Inspection report sent to permittee

Follow-Up Inspections				
Permit Number	Address	Type	Summary of Results	Communication
2018-48	5517-5525 Eden Prairie Rd, Minnetonka	Subdivision	Silt fence added and stock pile reduced	None

Totals

All values are estimates

Approximately 205 open permits with potential for activity

- Approximately 125 with activity
- Approximately 80 without activity