

**Nine Mile Creek Watershed District- Site Inspection Report  
January 2 through January 4, 2019**

**Inspection Summary**

Number of sites inspected = 67  
 Of inspected, # of sites with no current construction activity = 7  
 Of inspected, # of sites where construction has not started = 11  
 Of inspected, # of sites where no site issues were observed = 43  
 Of inspected, # of sites with action or follow-up required (see below) = 6

Permit #	Project Name	Date of Inspection	Observations	Status
2018-128	Home Construction: 6100 Ridgeway Rd.	3-Jan-2019	Foundation construction/concrete wall pouring in progress. Perimeter biologs could be inadequate to protect erosion for large on-site soil stockpile. <b>On-Site Contractor will observe for problems.</b>	Concerns noted for follow-up
2018-49	NE Penn Stormwater Storage Project	4-Jan-2019	Site excavation and stormwater culvert installation in progress. Inlet protection in place. Soil stockpiles will need perimeter control before spring thaw. <b>On-Site Contractor will have installed.</b>	Concerns noted for follow-up
2018-41	Acorn Mini Storage: Bloomington	4-Jan-2019	Landscaping activities in progress. Perimeter biologs have been removed during grading. <b>On-Site Contractor will have BMPs replaced.</b>	Concerns noted for follow-up
2018-07	Bloomington Self Storage: 9601 Penn Avenue South	4-Jan-2019	Building construction in progress. <b>Damaged perimeter silt fence will need to be repaired before spring thaw.</b>	Action required
2017-110	Southdale Shake Shack, SE Corner: West 66th & France Ave	4-Jan-2019	Building construction and landscaping complete. Vegetation not fully established.	Vegetation not fully established
2017-100	Bus Barn Site: 5150 Brookside and 5220 Eden Avenues	3-Jan-2019	Building construction in progress. <b>Minor sediment tracking to adjacent streets.</b> No major erosion-related issues observed.	Concerns noted for follow-up